## 2804 Pecos Improvements

## Plumbing/Drainage

- Replaced all caste iron piping with PVC (plumbing)
- Added significant drainage

## Exterior

- New roof
- New AC
- · Added pool and spa
- Enclosed sun room with AC/Heat and added marble flooring
- Added summer kitchen
- Repainted exterior where needed
- Repainted all exterior doors and sunroom doors
- Repainted front entry and added brand new photovoltaic (PV) lighting outdoor lanterns
- New landscaping
- Raised fencing height around the entire property, replaced rotted fence pieces, repainted entire fence
- Resurfaced driveway

## Other

- · Security cameras installed
- Alarm system